

Client's Name: City of Peoria	Site Location: Rain Garden	Project No. 13P150.02
---	--------------------------------------	---------------------------------

Photo No. 1	Date: 6/22/13
Direction Photo Taken: North	
Photo Taken By: AJK1	
Description: East side of the Rain Garden before maintenance/weeding	



Photo No. 2	Date: 6/22/13
Direction Photo Taken: North	
Photo Taken By: AJK1	
Description: West side of the Rain Garden before maintenance/weeding	



Client's Name: City of Peoria	Site Location: Rain Garden	Project No. 13P150.02
---	--------------------------------------	---------------------------------

Photo No. 3	Date: 6/22/13
Direction Photo Taken:	
Photo Taken By: AJK1	
Description: Before maintenance/weeding- orange flower is Butterfly weed	



Photo No. 4	Date: 6/22/13
Direction Photo Taken: North	
Photo Taken By: AJK1	
Description: West side of the Rain Garden during maintenance/weeding	



Client's Name: City of Peoria	Site Location: Rain Garden	Project No. 13P150.02
---	--------------------------------------	---------------------------------

Photo No. 5	Date: 6/22/13
Direction Photo Taken: North	
Photo Taken By: AJK1	
Description: East side of the Rain Garden during maintenance/weeding	



Photo No. 6	Date: 6/22/13
Direction Photo Taken: South	
Photo Taken By: AJK1	
Description: West side of the Rain Garden during maintenance/weeding	



Client's Name: City of Peoria	Site Location: Rain Garden	Project No.: 13P150.02
---	--------------------------------------	----------------------------------

Photo No.: 7	Date: 6/22/13
Direction Photo Taken: South	
Photo Taken By: AJK1	
Description: East side of the Rain Garden during maintenance/weeding	



Photo No.: 8	Date: 6/22/13
Direction Photo Taken: Northwest	
Photo Taken By: AJK1	
Description: West side of the Rain Garden during maintenance/weeding	



Client's Name: City of Peoria	Site Location: Rain Garden	Project No. 13P150.02
---	--------------------------------------	---------------------------------

Photo No. 9	Date: 6/22/13
Direction Photo Taken: Northwest	
Photo Taken By: AJK1	
Description: West side of the Rain Garden during maintenance/weeding	



Photo No. 10	Date: 6/22/13
Direction Photo Taken: North	
Photo Taken By: AJK1	
Description: East side of the Rain Garden after maintenance/weeding	



Client's Name: City of Peoria	Site Location: Rain Garden	Project No. 13P150.02
---	--------------------------------------	---------------------------------

Photo No. 11	Date: 6/22/13
Direction Photo Taken:	
Photo Taken By: AJK1	
Description: Maintenance Day Volunteers	



Photo No. 12	Date: 6/22/13
Direction Photo Taken:	
Photo Taken By: AJK1	
Description: Maintenance Day Volunteers	

